

Inspection Overview					
(SWT Central Plains Umbrella Mitigation Bank Site 3 - Little Blue)					
Date	Inspector	Frequency	Inspection Type	Boundaries Form(s)	
2018-02-14	KC	Annual	Site Inspection	See Easement Document	
General Information					
Origination Date	C.E. Authority & Type	Easement Size (Acres)	Owner's Name	Acknowledgment Date	Owner's Representative
2012-01-12	Sec 404 CWA	101.7	Swallow Tail, LLC		
Mitigation Bank					
Use Restrictions (Describe)					
See Section 4 of Easement Document					
Modifications Since Previous Inspection (Describe)					
N/A					
Threats to Conservation Value (Describe)					
None Found					
Inspection Findings (Describe)					
There appear to be no activities or occurrences on the premises, except as otherwise allowed.					